2. Specific questions:

No.	I. Company Name	II. Managing Company	III. Business Unit	IV. Shareholders	V. Country	VI. Operation
Anglo Americ	an Managed Operations					
40	Anglo American	Anglo American	IOB	Anglo American	Brazil	Minas Rio

1. "Tailings Facility" Name/identifier	2. Location	3. Ownership		operation	6. Is the Dam currently operated or closed as per currently approved design?
Serro da Sapo Tailings Dam	Latitude: 18°51′39″ S Longitude: 43°24′17″ W	Owned and Operated	Active	2014	Yes

7. Raising method	8. Current Maximum Height (m)	Storage Impoundment	10. Planned Tailings Storage Impoundment Volume in 5 years time (m³)	Independent Expert Review	complete relevant	13. What is your hazard categorisation of this facility, based on consequence of failure?	14. What guideline do you follow for the classification system?	its history, failed to be confirmed o certified as stable, or experienced notable stability concerns, as	external engineering support for this purpose?	
Downstream	41.5	43M	aprox. 135M (2024)	2018 & 2019 See Q20 for more information	Yes	Major	Anglo American Technical Standard (AA TS 602 001)		Both. Qualified, specialist operations team and Engineer of Record.	Yes, 2016

place for this dam, and b) does it include long term monitoring?	to assess your tailings	
Yes (conceptual level), Yes	Yes.	Q7: Dam is constructed as an earthfill (water retaining) type of a dam, with downstream sequential raising. Q11: September, 2018 - External Audit by engineering firm; January, 2019 - Technical Review Panel Report Q14: Anglo American Technical Standard AA TS 602 001 applied and implemented. Q19: Brazilian legislation requires complete dam safety reviews every 2, 3 or 5 years, according to the dam's classification. An update of hydrological data is part of the scope of the DSR. Also, Anglo American long term Sustainable Mining Plan requires this to be done for all managed sites within the next 2 years.