

**2. Specific questions:**

No.	I. Company Name	II. Managing Company	III. Business Unit	IV. Shareholders	V. Country	VI. Operation
Anglo American Managed Operations						
37	Anglo American	Anglo American	Copper	Anglo American; Inversiones Mineras Becrux SpA (Codelco/Mitsui); Mitsubishi	Chile	El Soldado

1. "Tailings Facility" Name/identifier	2. Location	3. Ownership	4. Status	5. Date of initial operation	6. Is the Dam currently operated or closed as per currently approved design?
Dam No. 4	Latitude: 32°39'31" S Longitude: 71°09'55" W	Operated by Anglo American for JV partners	Inactive	1970	Yes

7. Raising method	8. Current Maximum Height (m)	9. Current Tailings Storage Impoundment Volume (m <sup>3</sup> )	10. Planned Tailings Storage Impoundment Volume in 5 years time (m <sup>3</sup> )	11. Most recent Independent Expert Review	12. Do you have full and complete relevant engineering records including design, construction, operation, maintenance and/or closure.	13. What is your hazard categorisation of this facility, based on consequence of failure?	14. What guideline do you follow for the classification system?	15. Has this facility, at any point in its history, failed to be confirmed or certified as stable, or experienced notable stability concerns, as identified by an independent engineer (even if later certified as stable by the same or a different	16. Do you have internal/in house engineering specialist oversight of this facility? Or do you have external engineering support for this purpose?	17. Has a formal analysis of the downstream impact on communities, ecosystems and critical infrastructure in the event of catastrophic failure been undertaken
Downstream (main dam). Back dam built from rockfill in a single stage.	65 (Main wall)	53 M	53 M	2018, See Q20 for more information	Yes	Major (both walls)	Anglo American Technical Standard (AA TS 602 001)	No	Both. Qualified, specialist operations team and Engineer of Record.	Yes Main wall 2015, back wall 2019

18. Is there a) a closure plan in place for this dam, and b) does it include long term monitoring?	19. Have you, or do you plan to assess your tailings facilities against the impact of more regular extreme weather events as a result of climate change, e.g. over the next two years?	20. Any other relevant information and supporting documentation. Please state if you have omitted any other exposure to tailings facilities through any joint ventures you may have.
Yes (conceptual level), Yes	Yes, See Q20 for additional information	<p>Q1: Includes Main Wall and Back Dam. The main dam is 65 m high wall, constructed from compacted, cycloned sand and has been in care and maintenance since 1993. The back dam is a 17 m high earthfill dam with a rockfill shell and similarly has been in care and maintenance since 1993.</p> <p>Q11: Technical Review Panel, November 2018</p> <p>Q19: Not performed as yet, but Anglo American long term Sustainable Mining Plan requires this to be done for all managed sites within the next 2 years.</p>