## 2. Specific questions:

No.	I. Company Name	II. Managing Company	III. Business Unit	IV. Shareholders	V. Country	VI. Operation
Anglo Americ	an Managed Operations					
52	Angio American	Anglo Operations (Pty) Ltd.	Coal SA	Anglo American	South Africa	Goedehoop

1. "Tailings Facility" Name/identifier	2. Location	3. Ownership	4. Status	operation	6. Is the Dam currently operated or closed as per currently approved design?
Bank 5 Co-disposal	26.00.27 S : 29.27.30 E	Owned and Operated	Closed	1948	Yes

7. Raising method	o , ,	Storage Impoundment	10. Planned Tailings Storage Impoundment Volume in 5 years time (m³)	Independent Expert Review	complete relevant engineering records including design, construction, operation, maintenance and/or	categorisation of this facility, based on consequence of failure?	classification system?	•	engineering specialist oversight of this facility? Or do you have external engineering support for this purpose?	-
Other, See Q20 for more information	36	зм	3M	2012	Partial (final years of operation and closure)	High	Anglo American Technical Standard (AA TS 602 001)	,	Internal with external as required.	

18. Is there a) a closure plan		20. Any other relevant information and supporting documentation.
it include long term monitoring?	facilities against the impact of more regular extreme weather events as a result of	
	climate change, e.g. over the next two years?	
Yes and yes		Q7: Hybrid, Low height slimes compartment impoundment walls constructed uptream (8 m max). For the final 7 years of operation (2002-2009) the facility incorporated a formal slimes compartment, the outer impoundement wall was constructed upstream (8m max height) over previously downstream constructed walls (7m max height). The facility was formally closed in 2010 by reshaping and soil capping and cladding. Post closure monitoring includes the leaching of legacy pollution from beneath the footprint of the facility.