2. Specific questions:

No.	I. Company Name	II. Managing Company	III. Business Unit	IV. Shareholders	V. Country	VI. Operation
Anglo American Managed Operations						
1 <i>1 1</i>	-	Anglo Coal (Dawson Management) Pty Ltd		Anglo Coal (Dawson South) Pty Ltd; Mitsui Moura Investment Pty Ltd	Australia	Dawson

1. "Tailings Facility" Name/identifier	2. Location	3. Ownership		operation	6. Is the Dam currently operated or closed as per currently approved design?
Dawson Pit 2D TSF	24.556 S, 150.055 E	Operated by Anglo American for JV partners	Inactive	2002	No

7. Raising method	• , ,	Storage Impoundment	10. Planned Tailings Storage Impoundment Volume in 5 years time (m ³)	Independent Expert	complete relevant	13. What is your hazard categorisation of this facility, based on consequence of failure?	14. What guideline do you follow for the classification system?	its history, failed to be confirmed o certified as stable, or experienced	1 '	
					construction, operation, maintenance and/or closure.			identified by an independent engineer (even if later certified as stable by the same or a different		infrastructure in the event of catastrophic failure been undertaken
Other, See Q20 for more information	NA	855	Nil increase	2018	No design (see comments in Q20)	II OW / Minor	Queensland - Dept. of Env & Science/ Anglo American Technical Standard (AA TS 602 001)	No	Both	Yes, REMP 2018/2019. CCA as well as CCS completed

		20. Any other relevant information and supporting documentation.				
place for this dam, and b) does it include long term		Disease state if you have emitted any other expenses to tailings facilities through any joint contures you may have				
monitoring?	of more regular extreme	Please state if you have omitted any other exposure to tailings facilities through any joint ventures you may have.				
Q .	weather events as a result of					
	climate change, e.g. over the					
	next two years?					
Yes, Yes	No. Because the facility is disused and will be capped in next few years	Q4: Inactive pit in that, No tailings have been deposited in this in-pit storage since late 2005. Q6: It is planned to cap and rehabilitate this facility in accordance with "Mineral Residue Guideline" Doc #1069 Coal 7-9 Form. Q7: In Pit storage Q12: No design report. At the time of its operation however, relevant operational information, like the water balance model, storage levels, were available on Site. And further the storage was regulatory compliant during its operational life. Q17: Consequence classification for all the Dawson storages has been completed; using the Anglo-American's Standard AA TS 602 001. Q18: The closure plan is as per "Mineral Residue Guideline" DOC #1069_Coal_7-9 Form. This is at concept level however, the level of detail will be increased as the closure date becomes nearer.				