2. Specific questions:

No.	I. Company Name	II. Managing Company	III. Business Unit	IV. Shareholders	V. Country	VI. Operation	1. "Tailings Facility" Name/identifier	2. Location	3. Ownership	4. Status	5. Date of initial operation	6. Is the Dam currently operated or closed as per currently approved design?
Anglo American Managed Operations												
34	Anglo American	Anglo American	Copper	Anglo American; Inversiones Mineras Becrux SpA (Codelco/Mitsui); Mitsubishi	Chile	Los Bronces	Las Tortolas:	Latitude: 33°07'26" S Longitude: 70°43'56" W	Operated by Anglo American for JV partners	Active	1994	Yes

7. Raising method	8. Current Maximum Height (m)	9. Current Tailings Storage Impoundment Volume (m³)	10. Planned Tailings Storage Impoundment Volume in 5 years time (m³)	11.Most recent Independent Expert Review	12. Do you have full and complete relevant engineering records including design, construction, operation, maintenance and/or closure.	13. What is your hazard categorisation of this facility, based on consequence of failure?	14. What guideline do you follow for the classification system?	15. Has this facility, at any point in its history, failed to be confirmed or certified as stable, or experienced notable stability concerns, as identified by an independent engineer (even if later certified as stable by the same or a different	16. Do you have internal/in house engineering specialist oversight of this facility? Or do you have external engineering support for this purpose?	17. Has a formal analysis of the downstream impact on communities, ecosystems and critical infrastructure in the event of catastrophic failure been undertaken
Downstream (all dams)	100 (Main Wall) (see Q20 for additional information)	480 M	700 M	2018, See Q20 for more information	Yes	Major (all walls)	Anglo American Technical Standard (AA TS 602 001)	No	Both. Qualified, specialist operations team and Engineer of Record	Yes, 2015-2019

18. Is there a) a closure plan in place for this dam, and b) does it include long term monitoring?	19. Have you, or do you plan to assess your tailings facilities against the impact of more regular extreme weather events as a result of climate change, e.g. over the next two years?	20. Any other relevant information and supporting documentation. Please state if you have omitted any other exposure to tailings facilities through any joint ventures you may have.
Yes (conceptual level), Yes	Yes, See Q20 for additional information	Q1: Includes four walls: Main Wall (100 m max height), West Wall (48 m max. height) and East Wall (14 m max height) : downstream compacted cycloned sand walls. Plant wall (7 m max. height) : downstream earthfill (water retaining) wall. Future South Wall to come. Q11: Technical Review Panel, November 2018 Q19: Not performed as yet, but Anglo American long term Sustainable Mining Plan requires this to be done for all managed sites within the next 2 years. However, climate change is considered to be favourable for this facility, which is also capable of storing multiple PMFs.