2. Specific questions:

No.	I. Company Name	II. Managing Company	III. Business Unit	IV. Shareholders	V. Country	VI. Operation
Anglo Americ	an Managed Operations					
45	Anglo American	Anglo American	Nickel	Anglo American	Brazil	Codemin

1. "Tailings Facility" Name/identifier	2. Location	3. Ownership		operation	6. Is the Dam currently operated or closed as per currently approved design?
Codemin: Slag Pile No. 2	Latitude: 14°09'26''S Longitude: 48°20'36''W	Owned and Operated	Active.	2002	No.

7. Raising method	• , ,	Storage Impoundment	10. Planned Tailings Storage Impoundment Volume in 5 years time (m³)	Independent Expert Review	12. Do you have full and complete relevant engineering records including design, construction, operation, maintenance and/or closure.	categorisation of this facility, based on consequence of failure?		its history, failed to be confirmed o certified as stable, or experienced notable stability concerns, as	external engineering support for this purpose?	-
Dry Stack	60	3.8 M	2 M	2017, See Q20 for more information		High	Anglo American Technical Standard (AA TS 602 001)	,	Yes. Internal geologist-geotechnical expert. External support from a	