2. Specific questions:

No.		I. Company Name	II. Managing Company	III. Business Unit	IV. Shareholders	V. Country	VI. Operation
Δ n.c	ala Amoric	an Managed Operations					
AH	gio America	an Manageu Operations					
			Anglo Operations (Pty)				
54		Angio American	Ltd.	Coal SA	Anglo American	South Africa	Goedehoop

1. "Tailings Facility" Name/identifier	2. Location	3. Ownership		operation	6. Is the Dam currently operated or closed as per currently approved design?
Goedehoop Co-disposal	26.05.41 S : 29.25.43 E	Owned and Operated	Active	1982	Yes

· ·	, , ,	Storage Impoundment	10. Planned Tailings Storage Impoundment Volume in 5 years time (m³)	Independent Expert Review	complete relevant	13. What is your hazard categorisation of this facility, based on consequence of failure?	classification system?	its history, failed to be confirmed or certified as stable, or experienced notable stability concerns, as	external engineering support for this purpose?	•
Downstream, See Q20 for more information	54	*18.2M coarse; 9.8M fines	21.04M coarse; 10.55M fines	2013	Yes	Major	Anglo American Technical Standard (AA TS 602 001)	No	Both	Yes, Q4 2018

18. Is there a) a closure plan in place for this dam, and b) does		20. Any other relevant information and supporting documentation.				
		Please state if you have omitted any other exposure to tailings facilities through any joint ventures you may have.				
	Plan in place in line with Anglo American's Long term	Q7:Q9: Outer walls downstream, internal division wall centre line. Co-disposal facility where coarse discards are used to form an impoundment for the fines. Q10: Coarse discards on the facility are being remined for re-treatment, this is addressing LoM capacity concerns. Q17: The DBA did not include environmental impact. Q18: Closure plans are at concept level and will be developed in more detail closer to the closure date in accordance with the Anglo American process, inclusive of relevant long term monitoring.				